

## Vibrating Fans? Here's the quick fix.

### What is happening?

Sometimes from assembly the Misting Rings can be installed slightly off centre, this will cause the Ring to make contact with the outside casing of the Fan.



This will generally cause no issue when the Fan is operating alone, but when Mist is introduced from one of our High-Pressure Pumps, the action of the Pump forcing water through the lines will cause vibration. And you guessed it, the Mist Ring will vibrate and cause an irritating noise as it rubs the Fan casing.

### The Solution!

If the Mist Ring can not be manually adjusted so that it clears the through hole and makes no contact.

Contact OZmist and we will send out Rubber packing that can be used to dampen any vibration. This can be seen in the image below.



📞 1300 306 478

🌐 [ozmist.com.au](http://ozmist.com.au)

📍 31 Baker Street  
Wangaratta VIC 3677

